

Onsite Mock drill conducted on 29th November 2025 at Pather Dabi Mother Station, Jhanpa, Dist-Hooghly, West Bengal-741234 for handling the gas leakage from the flange joint of steel pipeline (Dia-3 Inches) in the upstream line of Compressor..



1. Fire Fighting by BGCL Fire Crew



2. Leakage rectification by O&M team.



3. "ZERO" LEL checked by Fire & Rescue controller, SIC .



4. Briefing by Fire and rescue controller after Mock drill.



5. Briefing by SIC after Mock drill.



6. Group Picture

End of Report